

A particle count comparison between 11 month old diesel and the same diesel after it had been flowed through the magnetic field of a model MB-1014 Mag-Boosta fuel conditioner for 2 hours. No filtration of any kind, was used in the system.

ISO 4406 particle count report – 26th February 2021 -Oilwatch Laboratories, Cape Town. Report numbers 666668 (without Mag-Boosta) and 666669 (with Mag-Boosta).

